

Dear KHANGAN/NANDHINIS.LO

Sanction No. SS4/A/101104 dated 10/06/2024 has been generated in reference to Service order No. 183859 dated 26/05/2024.

Area : SS4 COIMBATORE

Model : 40101701SD01374/SIC 18ITC5 WYS SPLIT

***** SRN *****

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01374 SIC 18ITC5 WYS SPLIT

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 240301374SA09865

Invoice No : 11145566

Invoice Date : 30/03/2024

DOP : 30/03/2024

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

PRA submitted by : DEEPAK K

Customer / Dealer Code : 40000E

Customer / Dealer Name : VASANTH & CO VASANTH & CO

Address : VASANTH & CO VASANTH & CO GUDOUN NO. 11 A/C SENTAL WAREHOUSE EVR

SALAI KK NAGAR TIRUCHI

City: K.K.NAGAR S.O

Telephone Number : 7824061080

Mobile Number : 7824061079

Observation text: GAS LEAK FOUND IN THE CONDENSOR COIL NON IDENT DEALER RC T

O CUST SO STOCK SO PROCESS REFUND KINDLY APPROVE

Approval remark: GAS LEAK CASE-CUST NOT ACCEPTING REPLACEMENT REPLACED THRU DEALER.

Sanction text: Gas leak problem in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.