

Dear KHANGAN/NANDHINIS.LO/ajayes

Sanction No. SS4/R/109426 dated 10/06/2024 has been generated in reference to Service order No. 413606 dated 30/05/2024.

Area : SS4 COIMBATORE

Model : 52141501SD03253/RD ERIOPLS 205B THF ST GL

Replacement Product Code : 52141501SD03253 RD ERIOPLS 205B THF ST GL

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD03253 RD ERIOPLS 205B THF ST GL

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 231103253DR00158

Invoice No : 11142050

Invoice Date : 08/02/2024

DOP : 08/02/2024

DEALER / CUSTOMER : DEALER

Damage/Defective : Damaged

Damage Happened During : Dealer / Retailer to Customer

Damaged Part(Only For Appl) : Cabinet,SidePanel

Accountable By : Dealer

Estimate Cost To Repair : Spares Rs. 5000 Labour Rs. 500 (Includes gas charging, if any)

Nature Of Problem : Top_Dealer_Trade_policy

Job Code Desc : CABINET#CABINET - DAMAGED/DENTS & SCRATCHES - SIDE PANEL REAR BOTTOM BUCKLING#APPLIANCE TO BE REPLACED

PRA submitted by : Kumaraselvan R

Customer / Dealer Code : 40000E

Customer / Dealer Name : EASHWEAR ELECTRONICS EASHWEAR ELECTRONICS

Address : EASHWEAR ELECTRONICS EASHWEAR ELECTRONICS SURANDAI MAIN ROAD THIRUKOIL NANTHVANAM NEAR ROUNDANAM SANKARANKOIL

City: Sankarankoil H O

Telephone Number : 9788133888

Mobile Number : 9095324554

Observation text: Erioplus leg buckling, Repair not possible Pls appr replacement from FG, Stk avl DOP: 08.02.24

Approval remark: SIDE PANEL BUCKLING- TRANSIT/HANDLING DAMAGES ERIO PLUS

Sanction text: cabinet damaged in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.