

Dear KHANGAN/ADHI

Sanction No. SS4/A/101047 dated 23/05/2024 has been generated in reference to Service order No. 183349 dated 21/05/2024.

Area : SS4 COIMBATORE

Model : 40101701SD01126/SIC 18TTC3-WWA Split

***** SRN *****

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01126 SIC 18TTC3-WWA Split

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 240401126SA12508GZ

Invoice No : 11104423

Invoice Date : 18/04/2024

DOP : 18/04/2024

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

PRA submitted by : Hiteshwaran G

Customer / Dealer Code : 40000E

Customer / Dealer Name : GIRIAS INVESTMENT PVT LTD GIRIAS INVESTMENT PVT LT

Address : GIRIAS INVESTMENT PVT LTD GIRIAS INVESTMENT PVT LTD NO 469, SEKALA

I ROAD NEAR PERIYAR STATUE KARAIKUDI

City: Karaikudi H O

Telephone Number : 6385896386

Mobile Number : 6385896386

Observation text: Main control car PCB not working Delr replace customer on approval/cus dop 11.05.24 SRN due to stock unavailability

Approval remark: CONTROL PCB DEFECT-CUST CASE- NOT ACCPETING REPAIR DOP MAY 24. REPLACED THRU DEALER.

Sanction text: Pcb problem in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.