

Dear KHANGAN/NANDHINIS.LO

Sanction No. SS4/A/101186 dated 10/07/2024 has been generated in reference to Service order No. 187734 dated 02/07/2024.

Area : SS4 COIMBATORE

Model : 40101701SD01277/SIC 18TTC3 GWD SPLIT

***** SRN *****

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01277 SIC 18TTC3 GWD SPLIT

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 240501277SA03265NZ

Invoice No : 11147757

Invoice Date : 21/05/2024

DOP : 21/05/2024

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

PRA submitted by : ABISHEGK.R

Customer / Dealer Code : 40000E

Customer / Dealer Name : LAXMI ELECTRONICS AND FURNITURE

Address : LAXMI ELECTRONICS AND FURNITURE NO.507,NEAR MGR SILAI, SALEM MAIN ROAD, VENGAMEDU, KARUR DST

City: VENGAMEDU S.O

Telephone Number : 8220589613

Mobile Number : 9362188088

Observation text: OUTDOOR PCB DEFECT AND NO STOCK FOR RC & SRN DONE PLEASE APPROVE THE SAME SIR.

Approval remark: odu pcb defect- CUST NOT ACCEPTING REPAIR CUST NOT ACCEPTING REPAIR. REPLACED THRU DEALER.

Sanction text: PCB problem in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.