

Dear KHANGAN/NANDHINIS.LO

Sanction No. SS4/R/109648 dated 13/07/2024 has been generated in reference to Service order No. 419869 dated 18/06/2024.

Area : SS4 COIMBATORE

Model : 41103015SD00031/GVR 99 L AC - LITE

Replacement Product Code : 41103015SD00034 MR VACCINE 99L AC 99L WHITE

Product Category : REFRIGERATOR

Defective Product Code : 41103015SD00031 GVR 99 L AC - LITE

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 210100031MR01908

Invoice No : NA

Invoice Date : 20/03/2021

DOP : 20/03/2021

DEALER / CUSTOMER : CUSTOMER

Damage/Defective : Defective

Nature Of Problem : Functional\_Defect\_-\_Not\_repairable

Job Code Desc : WATER LEAKAGE#LEAK FROM INNER CABINET#APPLIANCE TO BE REPLACED

PRA submitted by : Kumaraselvan R

Customer / Dealer Code : 40000E

Customer / Dealer Name : VARATHARAJAN VARATHARAJAN

Address : VARATHARAJAN VARATHARAJAN GEVERMENT PERMARIE HELTH CENTER ; PAN AGUDI ;TIRUNELVELI

City: PANAGUDI S.O

Telephone Number : 6382313122

Mobile Number : 9488327494

Observation text: Cabinet inner leak, Repair not possible, HO aprved Pls app r replacement from FG, Alt Stk avl DOP: 20.03.21

Approval remark: cabinet inner leak case- ILR HO APPROVAL IS ATTACHED

Sanction text: approved as per HO mail

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective service executive.