

Dear KHANGAN/NANDHINIS.LO

Sanction No. SS4/A/101264 dated 10/08/2024 has been generated in reference to Service order No. 690937 dated 05/08/2024.

Area : SS4 COIMBATORE

Model : 40101701SD00991/GIC 18DTC3-WVB SPLIT

Replacement Product Code : 40101701SD01442 SIC 18TTC3 WYQ SPLIT

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD00991 GIC 18DTC3-WVB SPLIT

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 220200991SA04700

Invoice No : 00

Invoice Date : 12/08/2023

DOP : 12/08/2023

DEALER / CUSTOMER : CUSTOMER

Damage/Defective : Defective

AC UNIT : IDU-ODU

ODU No : 220200991SA04691

Nature Of Problem : Repeat_Failure

Job Code Desc : CONDENSER - COPPER#UNABLE TO IDENTIFY LEAK#APPLIANCE TO BE REPLACED

PRA submitted by : DEEPAK K

Customer / Dealer Code : 40000E

Customer / Dealer Name : KISHORE KISHORE

Address : KISHORE KISHORE PLOT 39, SHANMUGHA NAGAR WEST EXTENCEN 24 TH CROSS, PRANSISH SCHL ROAD, THIRUCHY

City: Uyyakondanthirumalai B.O

Telephone Number : 9360779027

Mobile Number : 8220508542

Observation text: REPEAT GAS LEAK ISSUE AND LEAK CANT BE FOUND IN ODU CUST RAISED ISSUE IN ZENDISK ALT MODEL AVA KINDLY APPROVE

Approval remark: REPEAT GAS LEAK CASE-CUST NOT ACCEPTING REPAIR

Sanction text: Gas leak problem in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.