

Dear KHANGAN/NANDHINIS.LO/ajayes

Sanction No. SS4/R/109954 dated 20/08/2024 has been generated in reference to Service order No. 439031 dated 16/08/2024.

Area : SS4 COIMBATORE

Model : 52141501SD02749/RX EDGEPRO 205C TAF WN BS

Replacement Product Code : 52141501SD02749 RX EDGEPRO 205C TAF WN BS

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD02749 RX EDGEPRO 205C TAF WN BS

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 230702749DR00011

Invoice No : 11006517

Invoice Date : 30/06/2024

DOP : 30/06/2024

DEALER / CUSTOMER : DEALER

Damage/Defective : Damaged

Damage Happened During : Transit between Distributor to Dealer or viceversa

Damaged Part(Only For Appl) : Cabinet

Accountable By : Dealer

Estimate Cost To Repair : Spares Rs. 3000 Labour Rs. 100 (Includes gas charging, if any)

Nature Of Problem : Dealer\_Expectations\_-\_Not\_allowing\_Repairs

Job Code Desc : CABINET#CABINET - DAMAGED/DENTS & SCRATCHES - SIDE PANEL REAR BOTTOM BUCKLING#APPLIANCE TO BE REPLACED

PRA submitted by : DEEPAK K

Customer / Dealer Code : 40000E

Customer / Dealer Name : GOLDEN SPARES GOLDEN SPARES

Address : GOLDEN SPARES GOLDEN SPARES NO 5C, MG COMPLEX MADUARI ROAD PALAKARI TRICHI

City: Palakarai S.O

Telephone Number :

Mobile Number : 9047659853

Observation text: DENT FOUND THE SIDES OF THE MACHINE AND SPD IS NOT ALLOWING FOR REPAIR REQUESTING RC KINDLY APPROVE

Approval remark: BOTTOM BUCKLING-TRANSIT/HANDLING DAMAGES.

Sanction text: cabinet damaged in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective service executive.