

Dear KHANGAN/NANDHINIS.LO

Sanction No. SS4/A/101292 dated 16/09/2024 has been generated in reference to Service order No. 694511 dated 02/09/2024.

Area : SS4 COIMBATORE

Model : 40101701SD01256/DSS 12TI3R32-RWA SPLIT

***** SRN *****

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01256 DSS 12TI3R32-RWA SPLIT

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 231200010SA00148

Invoice No : 11090432

Invoice Date : 28/03/2024

DOP : 28/03/2024

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

PRA submitted by : ABISHEGK.R

Customer / Dealer Code : 40000E

Customer / Dealer Name : EVARIST ENGINEERING EVARIST ENGINEERING

Address : EVARIST ENGINEERING EVARIST ENGINEERING NO 209, NAMMANDHAN ROAD

ARISIPALAYAM

City: Arisipalayam

Telephone Number : 9442184853

Mobile Number : 9442184853

Observation text: CUSTOMER CASE-DEALER REPLACED TO CUSTOMER SEALED SYSTEM GAS LEAK. CUS DOP-12/04/2024 NO STOCK & SRN DONE. PLS APPROVE SIR

Approval remark: GAS LEAK - CUST CASE- NOT ACCEPTING REPAIR. REPLACED THRU DEALER.

Sanction text: sealed system problem in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.