Dear KHANGAN/NANDHINIS.LO

Sanction No. SS4/A/101356 dated 08/11/2024 has been generated in reference to Service order No. 699289 dated 13/10/2024.

Area: SS4 COIMBATORE

Model: 40101701SD01170/SIC 18DTC3-WWB SPLIT

Replacement Product Code: 40101701SD01126 SIC 18TTC3-WWA Split

 ${\tt Product\ Category\ :\ AIR\ CONDITIONER}$

Defective Product Code: 40101701SD01170 SIC 18DTC3-WWB SPLIT

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others): 240201170SA01170FM

Invoice No : 11145547
Invoice Date : 30/03/2024

DOP : 30/03/2024

DEALER / CUSTOMER : DEALER Damage/Defective : Defective

AC UNIT : IDU-ODU

ODU No : 240201170SA01763JZ

Nature Of Problem : Dealer_replaced_to_customer_approved_by_Service

Job Code Desc : IDU WATER DRIPPING / SWEATING#DRAIN PUMP CHOKE / NOT WORKING#A

PPLIANCE TO BE REPLACED

PRA submitted by : ABISHEGK.R

Customer / Dealer Code : 40000E

Customer / Dealer Name : BHARATH ELECTRONICS APPLIANCES BHARATH ELECTRONICS Address : BHARATH ELECTRONICS APPLIANCES BHARATH ELECTRONICS APPLIANCES NEW NO;440, SALEM ROAD, NEAR ROYAL ENFIELD SHOWROOM,

City: Namakkal H.O

Telephone Number: 9865248664 Mobile Number: 6384412264

Observation text: CUSTOMER CASE-DEALER REPLACED TO CUSTOMER IDU WATTER DRIPP

ING CASE-CUSTOMER ESCALATED AT DEALER POINT- CUSTOMER DOP-07/05/2024

Approval remark: WATER DRIPPING-CUST NOT ACCEPTING REPAIR. REPLACED THRU DEA LER.

Sanction text: Water leakage complaint in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.
- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective servic e executive.