

Dear KHANGAN/NANDHINIS.LO/ajayes

Sanction No. SS4/A/101423 dated 06/03/2025 has been generated in reference to Service order No. 728719 dated 22/02/2025.

Area : SS4 COIMBATORE

Model : 40101701SD01549/AC 1.5T SIC 18PTC3 WZT SPLIT
***** SRN *****

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01549 AC 1.5T SIC 18PTC3 WZT SPLIT

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 250100272SA02460KF

Invoice No : 11371009

Invoice Date : 31/01/2025

DOP : 31/01/2025

DEALER / CUSTOMER : DEALER

Damage/Defective : Damaged

PRA submitted by : KAMAL T

Customer / Dealer Code : 40000E

Customer / Dealer Name : FAMINA ELECTRONICS FAMINA ELECTRONICS

Address : FAMINA ELECTRONICS FAMINA ELECTRONICS 508/510 BIG BAZZER STREET F
AMINA COMPLEX DHARAPURAM TIRUPUR

City: DHARAPURAM H O

Telephone Number : 6382405009

Mobile Number : 9443732410

Observation text: CONDENSER COPPER TUBE LEAK ISSUE. DEALER REPLACED TO CUSTOMER, NO STOCK HENCE SRN APP CUST DOP : 06/02/2025. KINDLY APPROVE.

Approval remark: CONDENSER LEAK CASE- NEW CUST MACHINE. REPLACED THRU DEALER

Sanction text: condenser problem in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.