

Dear KHANGAN/NANDHINIS.LO

Sanction No. SS4/A/101443 dated 31/03/2025 has been generated in reference to Service order No. 221691 dated 10/03/2025.

Area : SS4 COIMBATORE

Model : 40101701SD01515/AC 1.5T SIC 18ITC5 WYD SPLIT
***** SRN *****

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01515 AC 1.5T SIC 18ITC5 WYD SPLIT

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 241100238SA00482AJ

Invoice No : 11161139

Invoice Date : 17/02/2025

DOP : 17/02/2025

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

PRA submitted by : ABISHEGK.R

Customer / Dealer Code : 40000E

Customer / Dealer Name : SRI AMARAVATHI ELECTRONIC SRI AMARVATHI ELECTRONIC

Address : SRI AMARAVATHI ELECTRONIC SRI AMARVATHI ELECTRONIC NO:132/1 VISHAL
TOWER BASEMENT KOVAI ROAD ; KARUR ;

City: Karur H O

Telephone Number : 9894659348

Mobile Number : 9629644339

Observation text: DEFECTIVE COMPLAINT- OUTDOOR PCB DEFECT & NOT WORKING. DEALER STOCKSET CASE.CUS DOP-07/03/2025 NO STOCK FOR RC & SRN DONE. PLS APPROVE SIR

Approval remark: odu pcb defect- CUST NOT ACCEPTING REPAIR REPLACED THRU DEALER

Sanction text: PCB problem in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.