

Dear KHANGAN/NANDHINIS.LO/ajayes

Sanction No. SS4/R/111196 dated 08/04/2025 has been generated in reference to Service order No. 373621 dated 12/03/2025.

Area : SS4 COIMBATORE

Model : 52141501SD03476/RD ERIOPLS 205A THF SS BL
***** SRN *****

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD03476 RD ERIOPLS 205A THF SS BL

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 241203476DR00992ZY

Invoice No : U24016616

Invoice Date : 04/01/2025

DOP : 04/01/2025

DEALER / CUSTOMER : DEALER

Damage/Defective : Damaged

PRA submitted by : D.SASIKUMAR

Customer / Dealer Code : 40000E

Customer / Dealer Name : THIRUMURUGAN FURNITURES AND ELECTRONICS

Address : THIRUMURUGAN FURNITURES AND ELECTRONICS NEHRU NAGAR SENTHURAI MAIN ROA NATHAM DINDUGAL

City: Natham S.O

Telephone Number : 8667866270

Mobile Number : 8667866270

Observation text: CABINET BOTTOM SIDE DAMAGE - REAR BOTTOM BUCKLING DUE TO SIDE BUCKLING, SRN APPLIED DOP - 04.01.2025. KINDLY APPROVE

Approval remark: BOTTOM BUCKLING-TRANSIT/HANDLING DAMAGES

Sanction text: cabinet damaged in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.