

Dear KHANGAN/NANDHINIS.LO/ajayes

Sanction No. SS4/U/100000 dated 07/06/2025 has been generated in reference to Service order No. 395883 dated 30/05/2025.

Area : SS4 COIMBATORE

Model : 48102103SD00002/VC EDXX 335X 1RNL RW  
\*\*\*\*\* SRN \*\*\*\*\*

Product Category : VIROSHIELD

Defective Product Code : 48102103SD00002 VC EDXX 335X 1RNL RW

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 241100002VC03348

Invoice No : 11007186

Invoice Date : 24/05/2025

DOP : 24/05/2025

DEALER / CUSTOMER : DEALER

Damage/Defective : Damaged

PRA submitted by : D.SASIKUMAR

Customer / Dealer Code : 40000E

Customer / Dealer Name : SRI SANIBAGAVAN ELECTRONICS SRI SANIBAGAVAN ELECTR

Address : SRI SANIBAGAVAN ELECTRONICS SRI SANIBAGAVAN ELECTRONICS NO 27/1 KI  
RSHNAPURAM COLONY 2ND ST MADHURAI

City: Krishnapuram Colony

Telephone Number : 9994891892

Mobile Number : 9994891892

Observation text: TOP SIDE BODY DAMAGE - TOP BODY BUCKLING DUE TO STOCK UNAV  
AILABILITY, SRN APPLIED DOP - 24.05.2025. KINDLY APPROVE

Approval remark: CABINET DAMAGED-TRANSIT HANDLING DAMAGES

Sanction text: cabinet damaged in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective service executive.