

Dear KHANGAN/NANDHINIS.LO

Sanction No. SS4/A/101566 dated 13/06/2025 has been generated in reference to Service order No. 148462 dated 10/06/2025.

Area : SS4 COIMBATORE

Model : 40101701SD01442/AC 1.5T SIC 18TTC3 WYQ Split
***** SRN *****

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01442 AC 1.5T SIC 18TTC3 WYQ Split

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 250100158SA04106IZ

Invoice No : NA

Invoice Date : 02/03/2025

DOP : 02/03/2025

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

PRA submitted by : D.SASIKUMAR

Customer / Dealer Code : 40000E

Customer / Dealer Name : MARIYAMMAL FURNICHER

Address : MARIYAMMAL FURNICHER NO252/2 KURUVIKULAM ROAD GAYATHRI HOTEL THIRUVENGADAM THENKASI

City: Tiruvengadam

Telephone Number : 8072884149

Mobile Number : 8072884149

Observation text: IDUPCB Failure Within 2 days of Installation (DOA) DUE TO CUST ESCALATION DEALER REPLACE, SRN APPLIED DOP - 03.03.2025. KINDLY APPROVE

Approval remark: IDU PCB DEFECT-CUST CASE-NOT ACCEPTING REPAIR MAR 2025 DOP
REPLACED THRU DEALER.

Sanction text: IDU PCB DEFECT

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.