

Dear NMS/SRINIR/ajayes

Sanction No. SS4/R/106869 dated 06/01/2023 has been generated in reference to Service order No. 367627 dated 17/12/2022.

Area : SS4 COIMBATORE

Model : 52141501SD01941/RX EDGEPRO 205C 33 WN BS

Replacement Product Code : 52141501SD01941 RX EDGEPRO 205C 33 WN BS

***** Replacement from Category Stock *****

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD01941 RX EDGEPRO 205C 33 WN BS

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 201001941DR00238

Invoice No : 11003903

Invoice Date : 04/02/2022

DOP : 04/02/2022

DEALER / CUSTOMER : CUSTOMER

Damage/Defective : Damaged

Damage Happened During : Transit from Branch to Dealer / Distributor / Cust

Damaged Part(Only For Appl) : Cabinet,

Accountable By : Transporter

Estimate Cost To Repair : Spares Rs. 2000 Labour Rs. 200 (Includes gas charging, if any)

Nature Of Problem : Functional_Defect_-_Not_repairable

Job Code Desc : CABINET#CABINET - DAMAGED/DENTS & SCRATCHES - SIDE PANEL DENT# APPLIANCE TO BE REPLACED

PRA submitted by : M.J.JUALEASH

Customer / Dealer Code : 40000E

Customer / Dealer Name : BASITH BASITH

Address : BASITH BASITH NO 4/340 TAMIL NAGAR PULIYADAM PALAYAM

City: Tirupur Bazaar S.O

Telephone Number : 9025784636

Mobile Number : 9655977714

Observation text: Cat replcmnt approved as spl case for damage in ref. as it was informed after 8 months. Approval mail attached. Inv dt-4/2/22.

Approval remark: REF DAMAGED CASE-APPROVED AS A SPECIAL CASE. TO BE REPLACED FROM CATEGORY STOCK. APPROVAL IS ATTACHED.

Sanction text: Approved for Category stock replacement

Kindly take necessary action.

SRINIR

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.