

Dear NMS/SRINIR

Sanction No. SS4/W/101738 dated 07/03/2023 has been generated in reference to Service order No. 392446 dated 05/03/2023.

Area : SS4 COIMBATORE

Model : 52141601SD00383/WTEON MGNS 70 5.0 FDTG MTBK

Replacement Product Code : 52141601SD00383 WTEON MGNS 70 5.0 FDTG MTBK

Product Category : WASHING MACHINE

Defective Product Code : 52141601SD00383 WTEON MGNS 70 5.0 FDTG MTBK

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 220500383FW00005

Invoice No : 11110741

Invoice Date : 30/09/2022

DOP : 30/09/2022

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

Nature Of Problem : Dealer_Expectations_-_Not_allowing_Repairs

Job Code Desc : WATER LEAKAGE#FROM SPIN TO WASH#ADJUSTED

PRA submitted by : ABISHEGK.R

Customer / Dealer Code : 40000E

Customer / Dealer Name : BHARATH ELECTRONIC BHARATH ELECTRONIC

Address : BHARATH ELECTRONIC BHARATH ELECTRONIC NO 228/5 THIRICHY MAIN ROAD
DADAGAPATTI B.O

City: Dadagapatti B.O

Telephone Number : 9489931370

Mobile Number : 9489931371

Observation text: DEFECTIVE CASE,DEALER STOCKSET COMPLAINT.WASH MOTO ELECTRI
CAL DEFECT/SHORT.DEALER WANT REPLACEMENT FOR THE SAME.PLEASE APPROVE SIR

Approval remark: WASH MOTOR DEFECT-DEALER STOCK SET CASE.

Sanction text: dealer damaged case

Kindly take necessary action.

GIRISHAM

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.