

Dear NMS/SRINIR

Sanction No. SS4/D/100159 dated 05/03/2023 has been generated in reference to Service order No. 390991 dated 28/02/2023.

Area : SS4 COIMBATORE

Model : 24131601SD00046 /DPFRZ GCHW110R6SHC HTOP WHITE

Replacement Product Code : 24131601SD00046 DPFRZ GCHW110R6SHC HTOP WHITE

Product Category : DEEP FREEZER

Defective Product Code : 24131601SD00046 DPFRZ GCHW110R6SHC HTOP WHITE

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 221000046CR00692

Invoice No : 11117115

Invoice Date : 01/02/2023

DOP : 01/02/2023

DEALER / CUSTOMER : CUSTOMER

Damage/Defective : Defective

Nature Of Problem : Customer\_Expectations\_-\_Not\_allowing\_Repairs

Job Code Desc : SEALED SYSTEM#CHOKE - CAPILLARY#APPLIANCE TO BE REPLACED

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : RAGUPATHY RAGUPATHY

Address : RAGUPATHY RAGUPATHY UPPULIAPPAN KOVIL SANNATHI, KOMBAKONAM;SRI MI  
THILA VIHAR KALYA MANDAPAMA

City: Tirunageswaram

Telephone Number : 9500181288

Mobile Number : 9500181288

Observation text: Gas Choke in sealed system Customer not allowing to repair  
-1-2-23 Appliance to be replaced

Approval remark: SEALED SYSTEM CHOKE-CUST CASE-DOP 1/2/23

Sanction text: Sealed system problem in the machine

Kindly take necessary action.

GIRISHAM

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective service executive.