Dear NMS/SRINIR

Sanction No. SS4/R/107260 dated 21/04/2023 has been generated in reference to Service order No. 403243 dated 08/04/2023.

Area: SS4 COIMBATORE

Model: 52141501SD02243/RD EDGERIO 207B 23 THF BH BL

Replacement Product Code: 52141501SD02243 RD EDGERIO 207B 23 THF BH BL

Product Category : REFRIGERATOR

Defective Product Code: 52141501SD02243 RD EDGERIO 207B 23 THF BH BL Cabinet No(For Appl) and SO/RPL/Invoice No(For Others): 221202243dr00250

Invoice No : na

Invoice Date : 19/03/2023

DOP : 19/03/2023

DEALER / CUSTOMER : CUSTOMER
Damage/Defective : Defective

Nature Of Problem : Customer_Expectations_-_Not_allowing_Repairs

Job Code Desc : CABINET#DRAIN BOX/ PAN DEFECTIVE#SECONDARY TRANSIT DAMAGE - WI

THIN POLICY

PRA submitted by : Marudhudurai R Customer / Dealer Code : 40000E

Customer / Dealer Name : REVATHY R R REVATHY R R

Address: REVATHY R R REVATHY R R NO:16, CHINNA STREET, PANDAMANGALAM,

WORIYUR,

City: WORIYUR

Telephone Number: 9715955953 Mobile Number: 9715955953

Observation text: Door is not locking properly Customer not allowing to repa

ir Appliance to be replaced

Approval remark: DOOR MISALIGNED-CUSTOMER NOT ACCEPTING REPAIR. DOP 19/3/23

Sanction text: Dealer defective case

Kindly take necessary action. GIRISHAM

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective servic e executive.