

Dear NMS/SRINIR

Sanction No. SS4/A/100670 dated 07/05/2023 has been generated in reference to Service order No. 394447 dated 06/04/2023.

Area : SS4 COIMBATORE

Model : 40101701SD01035/GSC 18PTC3-WVA

***** SRN *****

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01035 GSC 18PTC3-WVA

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 220201035SA01102

Invoice No : 11004131

Invoice Date : 07/04/2022

DOP : 07/04/2022

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

PRA submitted by : ABISHEGK.R

Customer / Dealer Code : 40000E

Customer / Dealer Name : ROYALHAIR CONDIGNOR SALES ROYALHAIR CONDIGNOR SALE

Address : ROYALHAIR CONDIGNOR SALES ROYALHAIR CONDIGNOR SALES NO;237/728,,SA

LEM MAIN ROAD NEW PUDHUPET NEAR KAKC PETROL BAUK

City: Krishnagiri H O

Telephone Number : 9361812802

Mobile Number : 9361812802

Observation text: CUSTOMER CASE-DEALER REPLACED TO CUSTOMER. SEADLED SYSTEM

GAS LEAK.CUSTOMER ESCALATED PURCHAS FROM OUR SPD-DOP-7/5/22.NO STCK FOR RC & SRN DONE

Approval remark: GAS LEAK - CUST CASE-MAY 22 PURCHASE. ESCALATED CASE

Sanction text: Gas leak problem in the machine

Kindly take necessary action.

GIRISHAM

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.