

Dear NMS/SRINIR

Sanction No. SS4/A/100681 dated 16/05/2023 has been generated in reference to Service order No. 396570 dated 21/04/2023.

Area : SS4 COIMBATORE

Model : 40101701SD00882/GIC 12DTC3-WUA SPLIT 3S

\*\*\*\*\* Refund \*\*\*\*\*

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD00882 GIC 12DTC3-WUA SPLIT 3S

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 211200882SA01551

Invoice No : 11095839

Invoice Date : 27/04/2022

DOP : 27/04/2022

DEALER / CUSTOMER : CUSTOMER

Damage/Defective : Defective

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : VIGNESH VIGNESH

Address : VIGNESH VIGNESH 3/1292 9TH STREET, THANDAIPERIYAR STREET, BHARAM A COLONY KARAUKUDI, SIVAGANGA DISTRICT

City: Karaikudi Southstreet S.O

Telephone Number : 7708912258

Mobile Number : 7010843299

Observation text: Gas leak in ODU condenser-27-4-22 Customer not allowing to repair SRN updated - No stock

Approval remark: ODU GAS LEAK CASE- CUST CASE- 27/4/2022 CUST NOT ACCEPTING REPAIR.

Sanction text: Gas leak problem in the machine

Kindly take necessary action.

GIRISHAM

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective service executive.