## Dear NMS/SRINIR

Sanction No. SS4/R/107409 dated 27/05/2023 has been generated in reference to Service order No. 416912 dated 18/05/2023.

Area: SS4 COIMBATORE

Model: 52141501SD01874/RT EONASTRA 305B 25 HI OX BL

Replacement Product Code : 52141501SD01874 RT EONASTRA 305B 25 HI OX BL

Product Category : REFRIGERATOR

Defective Product Code: 52141501SD01874 RT EONASTRA 305B 25 HI OX BL Cabinet No(For Appl) and SO/RPL/Invoice No(For Others): 211001874FR00138

Invoice No : 00

Invoice Date : 13/09/2022

DOP : 11/09/2022

DEALER / CUSTOMER : CUSTOMER Damage/Defective : Defective

Nature Of Problem : Customer\_Expectations\_-\_Not\_allowing\_Repairs

Job Code Desc : FAN MOTOR#NOISE - ABNORMAL NOISE#APPLIANCE TO BE REPLACED

PRA submitted by : Marudhudurai R Customer / Dealer Code : 40000E

Customer / Dealer Name : MOHAMMED RAFIK MOHAMMED RAFIK

Address: MOHAMMED RAFIK MOHAMMED RAFIK NO,45/2 KALLAMETTU STREET, NEAR SA VERIOR THIRUMANA MANDABAM, KALLAKUDI

City: Kallakudi Noth

Telephone Number: 9865825660 Mobile Number: 9384491229

Observation text: Fan motor defect -11-9-22 Cust not allowing to repair -M angal customer Appliance to be replaced

Approval remark: FAN MOTOR DEFECT-CUST CASE-NOT ACCEPTING REPAIR MANGAL & MA

Sanction text: Fan motor problem in the machine

Kindly take necessary action. GIRISHAM

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.
- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective servic e executive.