

Dear NMS/SRINIR

Sanction No. SS4/A/100747 dated 14/06/2023 has been generated in reference to Service order No. 401734 dated 29/05/2023.

Area : SS4 COIMBATORE

Model : 40101701SD00996/GIC 18TTC3-RVA

***** Refund *****

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD00996 GIC 18TTC3-RVA

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 220200996SA00247

Invoice No : 11004054

Invoice Date : 06/05/2023

DOP : 06/05/2023

DEALER / CUSTOMER : CUSTOMER

Damage/Defective : Defective

PRA submitted by : ABISHEGK.R

Customer / Dealer Code : 40000E

Customer / Dealer Name : D. REVATHI D. REVATHI

Address : D. REVATHI D. REVATHI NO; 41/1 MUSLIM ST PARATHEYAM THALUKKA NAMA
KKAL DIST

City: 637001

Telephone Number : 9500910200

Mobile Number : 8508811218

Observation text: DEFECTIVE CASE .CUSTOMER COMPLAINT,SEADLED SYSTEM GAS LEAK
& CUSTOMER NOT ALLOWED TECH TO REPAIR PLEASE APPROVE THE SAME SIR

Approval remark: GAS LEAK - CUST CASE-NEW MACHINE. CUST NOT ACCEPTING REPAIR

Sanction text: Gas leak problem in the machine

Kindly take necessary action.

GIRISHAM

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.