

Dear NMS/SRINIR

Sanction No. SS4/D/100189 dated 23/06/2023 has been generated in reference to Service order No. 427830 dated 17/06/2023.

Area : SS4 COIMBATORE

Model : 24131601SD00086/DH EPENTA 325C 31 CMFP2M RW

***** Refund *****

Product Category : DEEP FREEZER

Defective Product Code : 24131601SD00086 DH EPENTA 325C 31 CMFP2M RW

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 220500086CR03560

Invoice No : 00

Invoice Date : 09/09/2022

DOP : 09/09/2022

DEALER / CUSTOMER : CUSTOMER

Damage/Defective : Defective

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : MAKUTHURAJA MAKUTHURAJA

Address : MAKUTHURAJA MAKUTHURAJA ALWARKADAI FILOMENA SCHOOL OPPOSITE THANJ

AI MAIN ROAD KAATTUR TRICHY

City: Pappakurichi Kattur

Telephone Number : 8754144759

Mobile Number : 8754144759

Observation text: Gas leak in evaporator coil-9-9-22 Customer not allowing to repair Appliance to be replaced

Approval remark: GAS LEAK IN EVAPORATOR COIL-CUST CASE.

Sanction text: Gas leak problem in the machine

Kindly take necessary action.

GIRISHAM

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.