

Dear NMS/SRINIR

Sanction No. SS4/A/100777 dated 23/06/2023 has been generated in reference to Service order No. 403273 dated 10/06/2023.

Area : SS4 COIMBATORE

Model : 40101701SD01155/AC 1T SIC 12TTC3-WWA SPLIT 3S

***** Refund *****

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01155 AC 1T SIC 12TTC3-WWA SPLIT 3S

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 221201155SA07560

Invoice No : 16046651

Invoice Date : 28/01/2023

DOP : 28/01/2023

DEALER / CUSTOMER : CUSTOMER

Damage/Defective : Defective

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : VILSON VILSON

Address : VILSON VILSON HOTEL VILSON ,VELANGANNI NAAGAPATTINAM.

City: Vailankanni

Telephone Number : 9597158790

Mobile Number : 9597158790

Observation text: Leak in evaporator -28-1-23 Customer not allowing to repair-15AC purchased SRN updated - No stock

Approval remark: GAS LEAK - CUST CASE-NEW MACHINE.

Sanctiontext: Evaporator Gas leak problem in the machine

Kindly take necessary action.

GIRISHAM

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.