

Dear NMS/SRINIR

Sanction No. SS4/R/107585 dated 03/07/2023 has been generated in reference to Service order No. 426450 dated 14/06/2023.

Area : SS4 COIMBATORE

Model : 52141501SD02679/RD EMARVEL 207C 33 TDF AT BL

***** Refund *****

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD02679 RD EMARVEL 207C 33 TDF AT BL

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 221202679DR00061

Invoice No : xxxxxxxx

Invoice Date : 18/03/2023

DOP : 18/03/2023

DEALER / CUSTOMER : CUSTOMER

Damage/Defective : Defective

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : ARTHI ARTHI

Address : ARTHI ARTHI NO 26; GOVINDAMPILLAI ST; VEERASHWARAM; SRIRANGAM; TIRUCHY.

City: Srirangam H O

Telephone Number : 9585168241

Mobile Number : 7548819332

Observation text: Door misalignment - 18-3-23 Sweating issues inside ref due to gap Refund updated - No stock

Approval remark: DOOR ALIGNMENT -CUST CASE-NEW MACHINE. PRA APPROVED CASE/NO STOCK.

Sanction text: Door misalignment problem in the machine

Kindly take necessary action.

GIRISHAM

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.