

Dear NMS/SRINIR

Sanction No. SS4/A/100817 dated 21/07/2023 has been generated in reference to Service order No. 404566 dated 26/06/2023.

Area : SS4 COIMBATORE

Model : 40101701SD01126/SIC 18TTC3-WWA Split

***** SRN *****

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01126 SIC 18TTC3-WWA Split

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 221201126SA19972

Invoice No : 11117716

Invoice Date : 11/01/2023

DOP : 11/01/2023

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : DARLING TVC ELECTRONICS DARLING TVC ELECTRONICS

Address : DARLING TVC ELECTRONICS DARLING TVC ELECTRONICS NO 39 GROUNDED 1ST FLOOR NEW BUS STAND ROAD

City: Thanjavur City

Telephone Number : 7418857915

Mobile Number : 7418857915

Observation text: ODU Gas leak - 31-5-23 Dealer replaced to customer on approval SRN updated - No stock

Approval remark: GAS LEAK - CUST CASE- NOT ACCEPTING REPAIR. REPLACED THRU DEALER. NO FG STOCK FOR REPLACEMENT

Sanction text: Gas leak problem in the machine

Kindly take necessary action.

GIRISHAM

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.