

Dear NMS/SRINIR

Sanction No. SS4/A/100869 dated 19/09/2023 has been generated in reference to Service order No. 409456 dated 01/09/2023.

Area : SS4 COIMBATORE

Model : 40101701SD01254/SIC 12TTC3-WWA SPLIT 3S

\*\*\*\*\* SRN \*\*\*\*\*

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01254 SIC 12TTC3-WWA SPLIT 3S

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 230400008SA04237

Invoice No : 11016934

Invoice Date : 14/04/2023

DOP : 14/04/2023

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : SS ENTERPRISES SS ENTERPRISES

Address : SS ENTERPRISES SS ENTERPRISES NO 90 BATWARTH ROAD THIRICHY TEP  
PAKULAM

City: Teppakulam

Telephone Number : 9443371930

Mobile Number : 9443371930

Observation text: No Gas in ODU - 1-5-23-Distributor stock Dealer replaced to customer on approval SRN updated - No stock

Approval remark: NO GAS IN ODU AT THE TIME OF INSTALLATION. CUST NOT ACCEPTING REPAIR. REPLACED THRU DEALER. NO FG STOCK FOR REPLACEMENT.

Sanction text: Gas leak problem in the machine

Kindly take necessary action.

GIRISHAM

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective service executive.