

Dear NMS/SRINIR

Sanction No. SS4/A/100866 dated 19/09/2023 has been generated in reference to Service order No. 408879 dated 26/08/2023.

Area : SS4 COIMBATORE

Model : 40101701SD01254/SIC 12TTC3-WWA SPLIT 3S

***** SRN *****

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01254 SIC 12TTC3-WWA SPLIT 3S

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 230600008SA00639

Invoice No : 11093871

Invoice Date : 29/06/2023

DOP : 29/06/2023

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : GIRIYAS INVESTMENT GIRIYAS INVESTMENT

Address : GIRIYAS INVESTMENT GIRIYAS INVESTMENT NO;36A, TRICHY MAIN ROAD, VENKA VENKATESA PURAM, PERAMBALUR, CHENNAI

City: Perambalur

Telephone Number : 8939834222

Mobile Number : 8939834222

Observation text: Gas leak in ODU condensor-5-8-23 Dealer replaced to customer on approval SRN updated - No stock

Approval remark: GAS LEAK IN ODU CONDENSER-CUST CASE-DOP AUG 2023 REPLACED T HRU DEALER.

Sanction text: Gas leak problem in the machine

Kindly take necessary action.

GIRISHAM

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.