

Dear NMS/SRINIR

Sanction No. SS4/A/100879 dated 29/09/2023 has been generated in reference to Service order No. 409467 dated 01/09/2023.

Area : SS4 COIMBATORE

Model : 40101701SD00766/GSC 12OTC3-WSA

\*\*\*\*\* SRN \*\*\*\*\*

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD00766 GSC 12OTC3-WSA

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 190500766SA03457

Invoice No : 11035751

Invoice Date : 26/06/2019

DOP : 26/06/2019

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : VEMBU SONS VEMBU SONS

Address : VEMBU SONS VEMBU SONS NO 49; MADURAI ROAD; CONTONMENT; TRICHY;

City: Tiruchirappalli Cantt

Telephone Number : 9865458282

Mobile Number : 9865458282

Observation text: IDU Faded- EBO Vembu case discussed Customer not accept machine at demo SRN updated No stock

Approval remark: NOV 22 BILLED TO CUST CASE-VEMBUS SONS MR CHANDRAMOWLI ESCALATED AND FOLLOWING UP APPROVED AS A SPECIAL CASE.

Sanction text: Approved as a special case

Kindly take necessary action.

GIRISHAM

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective service executive.