

Dear NMS/SRINIR/ajayes

Sanction No. SS4/R/108136 dated 04/11/2023 has been generated in reference to Service order No. 341650 dated 02/11/2023.

Area : SS4 COIMBATORE

Model : 52141501SD03358/RD EMARVEL 207B TDF RL ST

Replacement Product Code : 52141501SD03358 RD EMARVEL 207B TDF RL ST

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD03358 RD EMARVEL 207B TDF RL ST

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 230603358DR00487

Invoice No : 11010346

Invoice Date : 03/10/2023

DOP : 03/10/2023

DEALER / CUSTOMER : DEALER

Damage/Defective : Damaged

Damage Happened During : Transit from Branch to Dealer / Distributor / Cust

Damaged Part(Only For Appl) : SidePanel,TopLidOrCover

Accountable By : Transporter

Estimate Cost To Repair : Spares Rs. 600 Labour Rs. 300 (Includes gas charging , if any)

Nature Of Problem : Dealer\_Expectations\_-\_Not\_allowing\_Repairs

Job Code Desc : CABINET#CABINET - DAMAGED/DENTS & SCRATCHES - TABLE TOP#APPLIAN  
CE TO BE REPLACED

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : RASI ELECTRONICS

Address : RASI ELECTRONICS NO: 39 CENTRAL RODE N.G.O.COLONY DINDIGUL

City: N.G.O.COLONY S.O

Telephone Number : 9840606143

Mobile Number : 9840606143

Observation text: Table top corner dent Non repairable Appliance to be replaced

Approval remark: CABINET DAMAGED FROM THE TOP-TRANSIT/HANDLING DAMAGES. NOT REPAIRABLE.

Sanction text: Cabinet damaged in the machine

Kindly take necessary action.

GIRISHAM

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective service executive.