

Dear NMS/SRINIR

Sanction No. SS4/R/108306 dated 06/12/2023 has been generated in reference to Service order No. 352691 dated 28/11/2023.

Area : SS4 COIMBATORE

Model : 52141501SD02976/RT EONVALOR 310B RCIT JD WN

\*\*\*\*\* SRN \*\*\*\*\*

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD02976 RT EONVALOR 310B RCIT JD WN

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 230102976FR00014

Invoice No : 11132708

Invoice Date : 08/08/2023

DOP : 08/08/2023

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : DARLING ELECTRONICS MOBILE AND FURNITURE

Address : DARLING ELECTRONICS MOBILE AND FURNITURE NO;40, ISWARYA MAHAL VADAK

U; VEETHI THIRUVARUR H O, TIRUVARUR

City: Thiruvarur H O

Telephone Number : 8072756312

Mobile Number : 8072756312

Observation text: Gas leak in sealer system - 31-8-23 Dealer replaced to customer on approval SRN updated - No stock

Approval remark: GAS LEAK - CUST CASE-NEW MACHINE. CUST NOT ACCEPTING REPAIR . REPLACED THRU DEALER.

Sanction text: gas leak problem in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective service executive.