

Dear NMS/SRINIR/ajayes

Sanction No. SS4/R/108269 dated 30/11/2023 has been generated in reference to Service order No. 351430 dated 24/11/2023.

Area : SS4 COIMBATORE

Model : 52141501SD03280/RD EDGEPRO 210D TDF MN WN

Replacement Product Code : 52141501SD03280 RD EDGEPRO 210D TDF MN WN

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD03280 RD EDGEPRO 210D TDF MN WN

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 230603280DR00790

Invoice No : 11132902

Invoice Date : 11/08/2023

DOP : 11/08/2023

DEALER / CUSTOMER : DEALER

Damage/Defective : Damaged

Damage Happened During : Transit from Branch to Dealer / Distributor / Cust

Damaged Part(Only For Appl) : SidePanel

Accountable By : Transporter

Estimate Cost To Repair : Spares Rs. 300 Labour Rs. 200 (Includes gas charging , if any)

Nature Of Problem : Not_repairable

Job Code Desc : CABINET#CABINET - DAMAGED/DENTS & SCRATCHES - SIDE PANEL DENT# APPLIANCE TO BE REPLACED

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : GIRIAS INVESTMENT PVT LTD GIRIAS INVESTMENT PVT LT

Address : GIRIAS INVESTMENT PVT LTD GIRIAS INVESTMENT PVT LTD 23;KARUR;BYPAS S MAIN ROAD; ANNAMALAI NAGAR , TIRUCHIRAPPALLI DT

City: Thillai Nagar S.O

Telephone Number : 8939970734

Mobile Number : 8939970734

Observation text: Side panel corner dent Non repairable Appliance to be replaced

Approval remark: SIDE PANEL DENT-TRANSIT/HANDLING DAMAGES. not repairable as back side cabinet is also dent

Sanction text: Dealer damaged case

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.