

Dear NMS/SRINIR

Sanction No. SS4/R/108315 dated 06/12/2023 has been generated in reference to Service order No. 350494 dated 21/11/2023.

Area : SS4 COIMBATORE

Model : 52141501SD01953/RD EDGE 205B 23 THF PP BL

Replacement Product Code : 52141501SD03253 RD ERIOPLS 205B THF ST GL

\*\*\*\*\* Replacement from Category Stock \*\*\*\*\*

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD01953 RD EDGE 205B 23 THF PP BL

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 220101953DR01426

Invoice No : 11111

Invoice Date : 19/12/2022

DOP : 19/12/2022

DEALER / CUSTOMER : CUSTOMER

Damage/Defective : Defective

Nature Of Problem : Fire/\_/Burnt\_Case

Job Code Desc : EXTERNAL FACTORS#FIRE - EXTERNAL FACTOR#APPLIANCE TO BE REPLACED

PRA submitted by : Kumaraselvan R

Customer / Dealer Code : 40000E

Customer / Dealer Name : SELVA RANI SELVA RANI

Address : SELVA RANI SELVA RANI NO : 2/214 ; VADAKU ST ; AMBALASERI ;

City: Ambalaseri B.O

Telephone Number : 8940312852

Mobile Number : 9344624472

Observation text: Fire incident approved by Mr. Rohit, Mail attached Pls app  
r replacement from category stock Cust DOP: 19.12.22

Approval remark: FIRE CASE- APPROVED BY HO.

Sanction text: Sanctioned as per Rohit mail for Category machine replacemen  
t Cabinet serial :231103253DR00288

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective service executive.