

Dear KHANGAN/ADHI

Sanction No. SS4/R/108633 dated 31/01/2024 has been generated in reference to Service order No. 368572 dated 15/01/2024.

Area : SS4 COIMBATORE

Model : 52141501SD01894/RF EON 236B 25 HI RY DR

Replacement Product Code : 52141501SD01894 RF EON 236B 25 HI RY DR

***** Replacement from Category Stock *****

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD01894 RF EON 236B 25 HI RY DR

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 210301894FR00433

Invoice No : na

Invoice Date : 03/08/2021

DOP : 03/08/2021

DEALER / CUSTOMER : CUSTOMER

Damage/Defective : Defective

Nature Of Problem : Functional_Defect_-_Not_repairable

Job Code Desc : ELECTRICAL POINT / WIRING / FUSE# CABINET INTERNAL WIRING SHORT / OPEN#APPLIANCE TO BE REPLACED

PRA submitted by : Kumaraselvan R

Customer / Dealer Code : 40000E

Customer / Dealer Name : Karthik Raja V Karthik Raja V

Address : Karthik Raja V Karthik Raja V SRIVALLIPUTTUR N SHANMUGASUGHARAP URAM KALI AMMAN KOVILL OPP SIT

City: Athikulam B.O

Telephone Number : 6369848018

Mobile Number : 8072490131

Observation text: Cabinet internal wiring open, Not repairable Pls appr RC from category stk, Rohit appr attached Cust DOP: 03.08.21

Approval remark: CABINET INTERNAL WIRING SHORT approved by HO TO BE REPLACED FROM CAT STOCK.

Sanction text: Approved as per Rohit mail Category stock replacement

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.