

Dear KHANGAN/ADHI

Sanction No. SS4/A/100974 dated 12/03/2024 has been generated in reference to Service order No. 600720 dated 07/03/2024.

Area : SS4 COIMBATORE

Model : 40101701SD01249/SIC 18TTC3 GWC

\*\*\*\*\* SRN \*\*\*\*\*

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01249 SIC 18TTC3 GWC

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 230401249SA00074

Invoice No : 11016934

Invoice Date : 14/04/2023

DOP : 14/04/2023

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : AMA ELECTRONICS AMA ELECTRONICS

Address : AMA ELECTRONICS AMA ELECTRONICS NO 198BTHIRUNALLAR ROAD KARAIKAL

City: KARAIKAL S.O

Telephone Number : 9942978686

Mobile Number : 9942978686

Observation text: Gas leak in ODU condenser-4-7-23 Distributor case-dealer replaced to customer SRN updated - No stock

Approval remark: GAS LEAK - CUST CASE- NOT ACCEPTING REPAIR.

Sanction text: gas leak problem in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective service executive.