

Dear KHANGAN/ADHI

Sanction No. SS4/R/108788 dated 25/02/2024 has been generated in reference to Service order No. 364697 dated 04/01/2024.

Area : SS4 COIMBATORE

Model : 52141501SD01383/RT EON 241 PC 3.4 SILKY BROWN

Replacement Product Code : 52141501SD01383 RT EON 241 PC 3.4 SILKY BROWN

***** Replacement from Category Stock *****

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD01383 RT EON 241 PC 3.4 SILKY BROWN

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 180401383FR00212

Invoice No : NA

Invoice Date : 14/01/2019

DOP : 14/01/2019

DEALER / CUSTOMER : CUSTOMER

Damage/Defective : Defective

Nature Of Problem : Fire/_/Burnt_Case

Job Code Desc : EXTERNAL FACTORS#FIRE - EXTERNAL FACTOR#APPLIANCE TO BE REPLAC ED

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : DHANALAKSHMI DHANALAKSHMI

Address : DHANALAKSHMI DHANALAKSHMI KAYALUR ARALUR POST TIRUTAN MARUDHUR TH ALUKKA ARALUR PAREYA SIT

City: Aralur B.O

Telephone Number : 9360985766

Mobile Number : 6381525087

Observation text: Fire originated from Fan motor connector HO approval attached Category stock to be replaced

Approval remark: FIRE CASE- APPROVED BY HO.

Sanction text: Approved as per Rohit mail For Category machine replacement

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.