

Dear KHANGAN/ADHI/ajayes

Sanction No. SS4/R/108983 dated 27/03/2024 has been generated in reference to Service order No. 391288 dated 22/03/2024.

Area : SS4 COIMBATORE

Model : 52141501SD03363/RD ERIOPLS 205C THF AZ BL

\*\*\*\*\* SRN \*\*\*\*\*

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD03363 RD ERIOPLS 205C THF AZ BL

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 231203363DR00904

Invoice No : 11142071

Invoice Date : 08/02/2024

DOP : 08/02/2024

DEALER / CUSTOMER : DEALER

Damage/Defective : Damaged

PRA submitted by : Kumaraselvan R

Customer / Dealer Code : 40000E

Customer / Dealer Name : SRI RAM FURNITURE SRI RAM FURNITURE

Address : SRI RAM FURNITURE SRI RAM FURNITURE NEAR BUS STAND, VIRUDHUNAGAR  
DST

City: VIRUDHUNAGAR H.O

Telephone Number : 9443142975

Mobile Number : 9443142975

Observation text: Erioplus Cabinet leg buckling, Not repairable Pls appr SRN  
under dlr policy, No FG Stk avl DOP: 08.02.24

Approval remark: CABINET DAMAGED FROM THE BASE- TRANSIT/HANDLING DAMAGES. LE  
G BUCKLING. NOT REPAIRABLE.

Sanction text: cabinet damaged in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective service executive.