

Dear KHANGAN/ADHI/ajayes

Sanction No. SS4/R/109014 dated 30/03/2024 has been generated in reference to Service order No. 392966 dated 27/03/2024.

Area : SS4 COIMBATORE

Model : 52141501SD03475/RD ERIOPLS 205A THF SS WN

***** SRN *****

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD03475 RD ERIOPLS 205A THF SS WN

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 240103475DR05050

Invoice No : 11141521

Invoice Date : 29/01/2024

DOP : 29/01/2024

DEALER / CUSTOMER : DEALER

Damage/Defective : Damaged

PRA submitted by : Avudi

Customer / Dealer Code : 40000E

Customer / Dealer Name : FAMINA ELECTRONICS FAMINA ELECTRONICS

Address : FAMINA ELECTRONICS FAMINA ELECTRONICS 509 BIG BAZZER STR.,

City: DHARAPURAM H O

Telephone Number : 6382405009

Mobile Number : 9443732410

Observation text: Erioplus Cabinet leg buckling, Not repairable Pls appr SRN as per dlr policy, No FG stk avl DOP: 29.01.24

Approval remark: CABINET DAMAGED FROM THE BASE-TRANSIT/HANDLING DAMAGES. LE G BUCKLING. NOT REPAIRABLE. ERIO PLUS

Sanction text: Cabinet damaged in the game

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.