Dear KHANGAN/ADHI

Sanction No. SS4/D/100237 dated 20/04/2024 has been generated in reference to Service order No. 394162 dated 31/03/2024.

Area: SS4 COIMBATORE

Model: 24131601SD00055/DH EPenta 325C 31CMFH2LM Rw

Replacement Product Code : 24131601SD00110 DH EPENTA 325D 2HCN RW

Product Category : DEEP FREEZER

Defective Product Code: 24131601SD00055 DH EPenta 325C 31CMFH2LM Rw Cabinet No(For Appl) and SO/RPL/Invoice No(For Others): 230300055CR00072

Invoice No : 11129607 Invoice Date : 01/07/2023

DOP: 01/07/2023

DEALER / CUSTOMER : CUSTOMER
Damage/Defective : Defective

Nature Of Problem : Customer_Expectations_-_Not_allowing_Repairs

Job Code Desc : COMPRESSOR#MOTOR-ELECTRICAL DEFECT#APPLIANCE TO BE REPLACED

PRA submitted by : AVUDAIAPPAN S Customer / Dealer Code : 40000E

Customer / Dealer Name : HARIHARAN HARIHARAN

Address: HARIHARAN HARIHARAN PAVILAM CAFE OPP SVR THEATRE THARAPURAM NE

AR BY NALLAMAI POLYTECHNIC

City: Dharapuram H O

Telephone Number: 9150926412 Mobile Number: 9944818449

Observation text: COMPRESSOR JAMMED- CUSTOMER NOT ALLOWING REPAIRS CUSTOMER

WANTS REPLACEMENT DOP 01.07.2023 FG REPLACEMENT

Approval remark: COMPRESSOR JAMMED-CUST NOT ACCEPTING REPAIRS

Sanction text: Compressor problem in the machine

Kindly take necessary action. ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.
- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective servic e executive.