

Dear KHANGAN/ADHI

Sanction No. SS4/A/101050 dated 24/05/2024 has been generated in reference to Service order No. 182276 dated 13/05/2024.

Area : SS4 COIMBATORE

Model : 40101701SD01216/SIC 18ITC5-WWR

\*\*\*\*\* SRN \*\*\*\*\*

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01216 SIC 18ITC5-WWR

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 240201216SA00001

Invoice No : 11143572

Invoice Date : 05/03/2024

DOP : 05/03/2024

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

PRA submitted by : ABISHEGK.R

Customer / Dealer Code : 40000E

Customer / Dealer Name : DARLING DIGITAL WORLD DARLING DIGITAL WORLD

Address : DARLING DIGITAL WORLD DARLING DIGITAL WORLD NO;56 ;/1 SOUTH KACHER I STREET ; RASI PURAM ;

City: Kakkaveri B.O

Telephone Number : 9994138388

Mobile Number : 9994083588

Observation text: CUSTOMER CASE,DEFECTIVE COMPLAINT. NEW AC OUTDOOR PCB NOT WORKING. CUSTOMER NOT ALLOWED TO REPAIR FURTHER. CUS DOP-31/03/2024.

Approval remark: PCB DEFECT-CUST CASE-NOT ACCEPTING REPAIR. DOP MAR 24

Sanction text: Pcb problem in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective service executive.