

Dear KHANGAN/ADHI/ajayes

Sanction No. SS4/R/109207 dated 17/05/2024 has been generated in reference to Service order No. 403374 dated 29/04/2024.

Area : SS4 COIMBATORE

Model : 52141501SD03331/RD ERIOPLS 205B THF SE WN

***** SRN *****

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD03331 RD ERIOPLS 205B THF SE WN

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 240203331DR01682

Invoice No : 11145661

Invoice Date : 03/04/2024

DOP : 03/04/2024

DEALER / CUSTOMER : DEALER

Damage/Defective : Damaged

PRA submitted by : Hiteshwaran G

Customer / Dealer Code : 40000E

Customer / Dealer Name : MARUTHY ELECTRONICS MARUTHY ELECTRONICS

Address : MARUTHY ELECTRONICS MARUTHY ELECTRONICS NO 245 , TRICHY ROAD ,
TURAIYUR , TRICHY

City: Turaiyur H.O

Telephone Number : 432722228

Mobile Number : 9943312280

Observation text: Cabinet side panel dent Dealer not allowing to repair

SRN due to stock unavailability

Approval remark: SIDE PANEL BUCKLING- TRANSIT/HANDLING DAMAGES NOT FEASIBLE
TO REPAIR.

Sanction text: cabinet damaged in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.