

Dear KHANGAN/NANDHINIS.LO/ajayes

Sanction No. SS4/A/101100 dated 10/06/2024 has been generated in reference to Service order No. 851127 dated 15/04/2024.

Area : SS4 COIMBATORE

Model : 40101701SD00780/SIC 18ITC5-WWA

***** SRN *****

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD00780 SIC 18ITC5-WWA

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 240200005SA01500

Invoice No : 11144580

Invoice Date : 18/03/2024

DOP : 18/03/2024

DEALER / CUSTOMER : DEALER

Damage/Defective : Damaged

PRA submitted by : DEEPAK K

Customer / Dealer Code : 40000E

Customer / Dealer Name : VEMBU SONS VEMBU SONS

Address : VEMBU SONS VEMBU SONS NO 49; MADURAI ROAD; CONTONMENT; TRICHY;

City: Tiruchirappalli Cantt

Telephone Number : 9865458282

Mobile Number : 9865458282

Observation text: GAS LEAK FOUND IN THE SYSTEM WITH IN 1 MONTH OF BILLING DE
ALER RC TO CUSTOMER NO STOCK HENCE REFUND PROCESSED

Approval remark: GAS LEAK-CUST CASE REPLACED THRU DEALER. EBO VEMBU SONS

Sanction text: Gas leak problem in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.