

Dear KHANGAN/NANDHINIS.LO

Sanction No. SS4/A/101166 dated 04/07/2024 has been generated in reference to Service order No. 187253 dated 26/06/2024.

Area : SS4 COIMBATORE

Model : 40101701SD01214/SFC 18PTC3-WWP

\*\*\*\*\* SRN \*\*\*\*\*

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01214 SFC 18PTC3-WWP

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 240101214SA02471

Invoice No : 11143135

Invoice Date : 28/02/2024

DOP : 28/02/2024

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

PRA submitted by : DEEPAK K

Customer / Dealer Code : 40000E

Customer / Dealer Name : SIR LUSHXME FURNECHAR SIR LUSHXME FURNECHAR

Address : SIR LUSHXME FURNECHAR SIR LUSHXME FURNECHAR NU 34 ;NEW STREET, MANAR KUDE, MANNARGUDITIRUVARUR

City: Kumbakonam Bazar

Telephone Number : 9487512457

Mobile Number : 9487512457

Observation text: CUSTOMER HAD LEAK IN THE CONDENSOR COIL AND NOT ALLOWING REPAIR SO DEALER PORCESSED RC TO CUST NO STOCK PLEASE APPORVE FOR SRN

Approval remark: GAS LEAK - CUST CASE- NOT ACCEPTING REPAIR. REPLACED THRU DEALER.

Sanction text: Gas leak problem in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective service executive.