

Dear KHANGAN/NANDHINIS.LO

Sanction No. SS4/A/101199 dated 15/07/2024 has been generated in reference to Service order No. 180747 dated 08/05/2024.

Area : SS4 COIMBATORE

Model : 40101701SD01277/SIC 18TTC3 GWD SPLIT

\*\*\*\*\* SRN \*\*\*\*\*

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01277 SIC 18TTC3 GWD SPLIT

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 240401277SA06544NZ

Invoice No : 11146398

Invoice Date : 23/04/2024

DOP : 23/04/2024

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

PRA submitted by : Hiteshwaran G

Customer / Dealer Code : 40000E

Customer / Dealer Name : SREE VIJAY ELECTRONIC SREE VIJAY ELECTRONIC

Address : SREE VIJAY ELECTRONIC SREE VIJAY ELECTRONIC NO:1977 2 B RAJA COMPL

EX WEST 4TH STREET PUDUKOTTAI

City: Pillaithannirpandal S.O

Telephone Number : 9715322357

Mobile Number : 9940112580

Observation text: Blower motor not working issue at cust place Delr rplcd to cust, dealer not allowing for repair SRN due to stock unavailability

Approval remark: BLOWER MOTOR CUST CASE REPLACED THRU DEALER.

Sanction text: approved as a special case

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective service executive.