## Dear KHANGAN/NANDHINIS.LO/ajayes

Sanction No. SS4/W/102571 dated 29/12/2024 has been generated in reference to Service order No. 352521 dated 27/12/2024.

Area: SS4 COIMBATORE

Model: 52141601SD00447/WTEON VLVT 70 5.0 FDTN2 MTBK

\*\*\*\*\* SRN \*\*\*\*\*

Product Category : WASHING MACHINE

Defective Product Code: 52141601SD00447 WTEON VLVT 70 5.0 FDTN2 MTBK Cabinet No(For Appl) and SO/RPL/Invoice No(For Others): 240900447FW01252ZL

Invoice No : 11156979
Invoice Date : 07/11/2024

DOP: 07/11/2024

DEALER / CUSTOMER : DEALER
Damage/Defective : Damaged
PRA submitted by : ABISHEGK.R
Customer / Dealer Code : 40000E

Customer / Dealer Name : DARILY INTER WORD DARILY INTER WORD

Address: DARILY INTER WORD DARILY INTER WORD 56/56SOURT KASTHER STERT NEAR

ANNAGER KOVIL City: Rasipuram Telephone Number:

Mobile Number: 9994138388

Observation text: CUSTOMER CASE-DEALER REPLACED TO CUSTOMER MAIN PCB DEFECT.

CUS DOP-18/11/2024 NO STOCK FOR RC & SRN DONE. PLS APPROVE SIR

Approval remark: MAIN PCB DEFECT-CUST CASE-CUST NOT ACCEPTING REPLACED THRU DEALER.

Sanction text: PCB problem in the machine

Kindly take necessary action. ADHI

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.
- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective servic e executive.