

Dear KHANGAN/NANDHINIS.LO/ajayes

Sanction No. SS4/R/111137 dated 26/03/2025 has been generated in reference to Service order No. 373936 dated 13/03/2025.

Area : SS4 COIMBATORE

Model : 52141501SD03328/RD ERIOPLS 205B THF ST GL
***** SRN *****

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD03328 RD ERIOPLS 205B THF ST GL

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 241003328DR00347PZ

Invoice No : 11007298

Invoice Date : 11/11/2024

DOP : 11/11/2024

DEALER / CUSTOMER : DEALER

Damage/Defective : Damaged

PRA submitted by : D.SASIKUMAR

Customer / Dealer Code : 40000E

Customer / Dealer Name : SREE VENKADESHWARA FURUNITURE

Address : SREE VENKADESHWARA FURUNITURE NO 175 MAIN ROAD NEAR INDIAN BANK SATHUR

City: Sattur

Telephone Number : 9600884562

Mobile Number : 9600884562

Observation text: RIGHT SIDE DOOR DAMAGE - RIGHT SIDE DOOR BUCKLING DUE TO S TOCK UNAVAILABILITY, SRN APPLIED DOP - 11.11.2024. KINDLY APPROVE

Approval remark: DOOR DENT- TRANSIT HANDLING DAMAGES

Sanction text: door damaged in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.