

Dear KHANGAN/NANDHINIS.LO/ajayes

Sanction No. SS4/R/110984 dated 07/02/2025 has been generated in reference to Service order No. 364238 dated 03/02/2025.

Area : SS4 COIMBATORE

Model : 41103015SD00027/MR GBR 225L AE WHITE

Replacement Product Code : 41103015SD00027 MR GBR 225L AE WHITE

Product Category : REFRIGERATOR

Defective Product Code : 41103015SD00027 MR GBR 225L AE WHITE

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 201000027MR00047

Invoice No : na

Invoice Date : 07/01/2021

DOP : 07/01/2021

DEALER / CUSTOMER : CUSTOMER

Damage/Defective : Damaged

Damage Happened During : Transit from Branch to Dealer / Distributor / Cust

Damaged Part(Only For Appl) : Cabinet

Accountable By : Transporter

Estimate Cost To Repair : Spares Rs. 1000 Labour Rs. 200 (Includes gas charging, if any)

Nature Of Problem : Customer\_Expectations\_-\_Not\_allowing\_Repairs

Job Code Desc : WATER LEAKAGE#LEAK FROM INNER CABINET#APPLIANCE TO BE REPLACED

PRA submitted by : KAMAL T

Customer / Dealer Code : 40000E

Customer / Dealer Name : PRIMARY HEALTH CENTRE

Address : PRIMARY HEALTH CENTRE HELATH DIRETER HELATH SERICES SANMUGA NAGE R KOVIL PATTI

City: Kovilpatti H.O

Telephone Number : 6385083359

Mobile Number : 9943647984

Observation text: INTERNAL CABINET LEAK PROBLEM. MED REF, SR.NO & VID ATTACH ED. CUST DOP : 07/01/21. KINDLY APPROVE.

Approval remark: internal cabinet leak-cust case

Sanction text: Approved as a special case

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective service executive.