

Dear KHANGAN/NANDHINIS.LO

Sanction No. SS4/A/101520 dated 20/05/2025 has been generated in reference to Service order No. 143824 dated 05/05/2025.

Area : SS4 COIMBATORE

Model : 40101701SD01442/AC 1.5T SIC 18TTC3 WYQ Split
***** SRN *****

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01442 AC 1.5T SIC 18TTC3 WYQ Split

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 240800158SA25943SZ

Invoice No : 11162860

Invoice Date : 25/03/2025

DOP : 25/03/2025

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

PRA submitted by : KAMAL T

Customer / Dealer Code : 40000E

Customer / Dealer Name : DARLING TVC ELECTRONICS DARLING TVC ELECTRONICS

Address : DARLING TVC ELECTRONICS DARLING TVC ELECTRONICS NO:12, THANJAVUR MA IN ROAD, BALAJI NAGAR, TIRUVARAMBUR,

City: Pappakurichi Kattur

Telephone Number : 9080059881

Mobile Number : 9080059881

Observation text: SEALED SYSTEM,GAS LEAK PROBLEM. SR.NO IMG ATTACHED DEALER REPLACED TO CUSTOMER. SR.NO&BILL IMG ATTAC CUST DOP : 24/04/2025. KINDLY APPROVE.

Approval remark: SEALED SYSTEK GAS LEAK-CUST CASE NEW CUST CASE REPLACED THRU DEALER.

Sanction text: SEALED SYSTEK GAS LEAK

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.