

Dear KHANGAN/NANDHINIS.LO

Sanction No. SS4/W/102789 dated 23/05/2025 has been generated in reference to Service order No. 393643 dated 22/05/2025.

Area : SS4 COIMBATORE

Model : 52141601SD00420/WTEON VLVT 75 5.0 FDTN MTBK

\*\*\*\*\* SRN \*\*\*\*\*

Product Category : WASHING MACHINE

Defective Product Code : 52141601SD00420 WTEON VLVT 75 5.0 FDTN MTBK

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 240800420FW00877ZV

Invoice No : 11153322

Invoice Date : 30/08/2024

DOP : 30/08/2024

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

PRA submitted by : ABISHEGK.R

Customer / Dealer Code : 40000E

Customer / Dealer Name : BHARATH ELECTRONICS BHARATH ELECTRONICS

Address : BHARATH ELECTRONICS BHARATH ELECTRONICS NO:10/1,DEVI GANESH COMPLEX, MEIYANUR ROAD, SELAM NEAR-THREE ROAD, SALEM,

City: Meyyanur

Telephone Number : 8012548668

Mobile Number : 8012548668

Observation text: DEFECTIVE COMPLAINT- MAIN PCB DEFECT & NOT WORKING DEALER REPLACED TO CUSTOMER. CUSTOMER DOP-28/9/24 NO STOCK FOR RC & SRN DONE. PLS APPROVE SIR

Approval remark: main pcb defect-cust case-not accepting repair REPLACED THR U DEALER.

Sanction text: main pcb defect

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective service executive.