

Dear KHANGAN/NANDHINIS.LO

Sanction No. SS4/A/101536 dated 27/05/2025 has been generated in reference to Service order No. 146163 dated 19/05/2025.

Area : SS4 COIMBATORE

Model : 40101701SD01445/AC 1.5T SIC 18DTC3 WYQ SPLIT
***** SRN *****

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01445 AC 1.5T SIC 18DTC3 WYQ SPLIT

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 241000161SA03809TZ

Invoice No : 11160537

Invoice Date : 31/01/2025

DOP : 31/01/2025

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

PRA submitted by : RAMESH V

Customer / Dealer Code : 40000E

Customer / Dealer Name : MAHARAJA PAATHIRA KADAI & FURNITURE

Address : MAHARAJA PAATHIRA KADAI & FURNITURE A1 VILLANGARA THERU ARIYALUR

City: Ariyalur S.O

Telephone Number : 9443837276

Mobile Number : 9443837276

Observation text: SEALED SYSTEM GAS LEAK PROBLEM DEALER REPLACED TO CUSTOMER
MACHINE CUSTOMER DOP 25.04.2025

Approval remark: SEALED SYSTEK GAS LEAK-CUST CASE APR 2025 DOP REPLACED T
HRU DEALER.

Sanction text: sealed system problem in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.